

BMW Group - AIR: 2026-09-14 / 20:48
Retailer: 32711/06
Model: X5 xDrive40d
Vehicle identification number: **VIN HIDDEN**
Development code: G05
Model code: TH41
Lead type: TH41

Vehicle

BMW X5 xDrive40d, 250KW
VIN HIDDEN



Development code G05
Colour arktis-grau Brillanteffekt
Actual integration level S18A-25-07-562
Start of warranty 2 November 2022

▼ Technical campaigns

There are no Campaigns for this vehicle.

▼ Special information

There are no Campaigns for this vehicle.

▼ Live Diagnosis

 There are no service solutions for Live Diagnosis.

▼ Service contracts

No BSI contracts

▼ Information on faults workshop/Service Consultation

There is no information on faults.

▼ Navigation map

Installed map	Enabling code (subscription)	Latest navigation map included in subscription	Latest navigation map subject to charge
Road Map EUROPE Live 2021-4 (As of: 23 Feb 2026)	Enabling code valid for navigation maps with release date up to 31 Dec 2099 (SWID: 01559912).	Road Map EUROPE Live 2026-3	-

▼ Vehicle details

Vehicle type Passenger car

Brand	BMW
Model	X5 xDrive40d
Body	GEFZG
Vehicle identification number (last 7 digits)	VIN HIDDEN
Vehicle identification number (17 digits)	VIN HIDDEN
Development code	G05
Steering	LL
Engine	XD5T
Engine number	55676679
Exhaust re-treatment	EURO 6 AP
Transmission	AUT
Transmission number	0744376WL5
Head unit serial number	HBB493N712MNIV
Drive	ALLR
Integration level, works	S18A-21-11-560
Production date	25 Feb 2022
Production plant	Spartanburg
Delivery date	22 Apr 2022
Delivering retailer	Niederlassung Frankfurt, Frankfurt am Main, DE
National-market version	EUR
Paint code	C27
Upholstery code	MCRI
Model code	TH41
Basic type	TH41
Lead type	TH41

Optional equipment

Optional equipment ex works:

01CB CO2 equipment
01CE Recuperation system
01MA M sports exhaust system
01XN 21" LA wheel Y-spoke 741M emerg.op.
0230 EU-specific additional contents
0258 Tyres with runflat properties
02NH M Sport brake
02PA Locking wheel bolt
02TB Sport automatic gearbox
02VB Tyre pressure display
02VF Adaptive M chassis
02VH Integral active front steering
0302 Alarm system
0322 Comfort access
0337 M Sports package
03DS BMW display key
03KA Acoustic comfort glazing
03MC M roofrailing, Shadow Line

Retrofitted optional equipment:

03AC Trailer coupling
DEBP PCU48GEN1 RSU

03MF M lights Shadow Line
 0407 Sky Lounge panoramic glass sunroof
 0413 Luggage compartment net
 0420 Sun protection glazing
 0423 Floor mats velours
 0428 Warning triangle and first aid kit
 0459 Seat adjustment, electric, with memory
 0481 Sports seat
 04AW Instrument panel Sensatec
 04HA Seat heating, front and rear
 04HB Heat comfort package, front
 04MC Interior trimstrips, Carbon Fibre
 04NB Autom. climate control with 4-zone ctrl
 04NM Ambient Air Paket
 04T8 Extended mirror package
 04UR Ambient interior light
 0536 Auxiliary heating
 0548 Kilometre speedo
 05AC High-beam assistant
 05AQ Active guard plus
 05AU Driving assistant professional
 05AZ BMW Laserlicht
 05DN Parking assistance system Plus
 0610 Head-up display
 0654 DAB tuner
 0688 Harman/Kardon surround sound system
 06AE Teleservices
 06AF Statutory emergency call
 06AK Connected Drive Services
 06C4 Connected Package Professional
 06NW Telephony with wireless charging
 06P1 Temp.deletion BMW Remote SoftwareUpgrade
 06U3 BMW Live operating area Professional
 06WD WLAN Hotspot
 0710 M leather steering wheel
 0715 M Aerodynamics package
 0760 High gloss shadow line
 0775 Headlining anthracite
 07M9 M Shadow Line with expanded scope
 07R7 Innovation package
 0801 German version
 0851 Language version German
 0879 On-board literature, German
 08KA Oil service interval 24 mths / 30,000 km
 08R9 Refrigerant R1234yf
 08TF Active pedestrian protection
 0925 Dummy-SALAPA
 09AA Outer skin protection
 A090 90 Ah AGM battery

▼ Control unit software version

Note: Permitted CAL ID/CVN combinations in EURO vehicles.

Control unit	Control unit class	CAL ID	CVN
DDE	DDE	025C17CC	025C17CC
		0A0D81DE	0A0D81DE
		0B520319	0B520319
		16F7BE54	16F7BE54
		1E3B802B	1E3B802B
		2064959E	2064959E
		2064959E00000000	2064959E
		2B9820CC	2B9820CC
		38286E4B	38286E4B
		3E14FFBD	3E14FFBD

		3E14FFBD00000000	3E14FFBD
		462C33E6	462C33E6
		4703B26E	4703B26E
		519A1367	519A1367
		519A136700000000	519A1367
		51FC2579	51FC2579
		52A697C0	52A697C0
		52A697C000000000	52A697C0
		547D1157	547D1157
		55366319	55366319
		713606AC	713606AC
		75FC40CC	75FC40CC
		7EF6DB04	7EF6DB04
		7EF6DB0400000000	7EF6DB04
		7FEE7CFC	7FEE7CFC
		8A3D5D2E	8A3D5D2E
		A323C58D	A323C58D
		A323C58D00000000	A323C58D
		AAF77EFB	AAF77EFB
		B306FB7A	B306FB7A
		B306FB7A00000000	B306FB7A
		B4762DF1	B4762DF1
		B4762DF100000000	B4762DF1
		B4BAB7BB	B4BAB7BB
		B7E55616	B7E55616
		BAD94A26	BAD94A26
		BCE5DBD0	BCE5DBD0
		C6AC6BE9	C6AC6BE9
		E308A994	E308A994
		E463CCF8	E463CCF8
		E463CCF800000000	E463CCF8
		E48CADFD	E48CADFD
		E54C4D70	E54C4D70
		E54C4D7000000000	E54C4D70
		EDAC028C	EDAC028C
DME1	DME	0B520319	0B520319
		2B9820CC	2B9820CC
		51FC2579	51FC2579
		547D1157	547D1157
		55366319	55366319
		713606AC	713606AC
		75FC40CC	75FC40CC
		7FEE7CFC	7FEE7CFC
		8A3D5D2E	8A3D5D2E
		AAF77EFB	AAF77EFB
		BAD94A26	BAD94A26
		C6AC6BE9	C6AC6BE9

▼ Vehicle histories

	Date	Type	Vehicle mileage			Retailer	Overview				
—	23/02/2026	Key	165681 Km			27164	Key 10				
	 15000 11/2027	 15000 11/2027	 15000 11/2027	 15000 11/2027	 -4800 6.5 %	 01/2027	 01/2027	 15000 11/2027			
—	23/02/2026	Service	165681 Km			27164 Muzzolini, Esch-Sur- Alzette	Automatic				
	 11/2027	 11/2027	 11/2027	 11/2027	 ✓	 01/2027	 01/2027	 11/2027			
											
—	23/02/2026	Repair	165681 Km			27164 ,	Job				
— Job											
Description: Service freins avant complet											
Considered as a repeat visit No											
Customer's own words											
Service, front brakes 8 FRU											
Flat rate unit I 00 00 612											
Removing and installing or replacing both front brake discs 4 FRU											
Flat rate unit I 34 11 613											
Performing vehicle test 2 FRU											
Flat rate unit I 00 00 556											
Job time without allowance for / maintenance 2 FRU											
Flat rate unit I 00 99 000											
Repair kit, brake pads asbestos-free 1											
Part I 34 11 6 889 585											
Brake pad wear sensor, front 1											
Part I 34 35 6 870 353											
Brake disc, lightweight,ventilated,right 1											
Part I 34 10 6 887 398											
Brake disc, lightweight, ventilated,left 1											
Part I 34 11 6 887 397											
—	13/01/2026	Key	157487 Km			27164	Key 10				

 23000 11/2027	 23000 11/2027	 23000 11/2027	 23000 11/2027	 4000 11/2027	 01/2027	 01/2027	 01/2027	 23000 11/2027
--	--	--	--	---	---	---	--	--

— 16/12/2025 Key 154602 Km 27164 Key 10

 27000 11/2027	 27000 11/2027	 27000 11/2027	 27000 11/2027	 11/2027	 01/2027	 01/2027	 11/2027	 27000 11/2027
---	---	---	---	--	--	--	---	---

— 16/12/2025 Repair 154602 Km 27164 , ESCH-SUR-ALZETTE Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Checking function of transfer box 6 FRU
Flat rate unit | 27 00 000

Exchanging transfer box 55 FRU
Flat rate unit | 27 10 520

Programming/encoding control unit(s) including deleting fault memories 4 FRU
Flat rate unit | 61 00 730

Performing vehicle test 3 FRU
Flat rate unit | 00 00 556

Transfer box 1
Part | 27 10 7 889 034

Gearbox mount 1
Part | 22 32 7 935 122

— 09/12/2025 Key 153416 Km 27164 Key 10

 29000 11/2027	 29000 11/2027	 29000 11/2027	 29000 11/2027	 11/2027	 01/2027	 01/2027	 11/2027	 29000 11/2027
---	---	---	---	--	--	--	---	---

— 17/11/2025 Key 151876 Km 27164 Key 10

 30000 11/2027	 30000 11/2027	 30000 11/2027	 30000 11/2027	 11/2027	 01/2027	 01/2027	 11/2027	 30000 11/2027
---	---	---	---	--	--	--	---	---

— 17/11/2025 Repair 151876 Km 27164 , ESCH-SUR-ALZETTE Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 006	4 FRU
Vehicle diagnosis - carrying out the ABL Flat rate unit I 61 00 006	2 FRU
Replacing servomotor for exhaust gas recirculation cooler switchover flap Flat rate unit I 11 71 535	6 FRU
Continuing vehicle test and deleting fault memory Flat rate unit I 61 00 980	2 FRU
unknown fru: Essai/Contrôle final Flat rate unit I 00 99 001	Local2 FRU
Linear actuator Part I 11 71 8 476 983	2
Valve pushrod Part I 11 71 8 476 980	2

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace right rear light of tailgate Flat rate unit I 63 21 282	11 FRU
Checking lighting system for correct operation Flat rate unit I 63 00 009	1 FRU
Rear light tailgate LED right Part I 63215A0DB06	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test Flat rate unit I 00 00 556	2 FRU
Removing and installing front bumper panel Flat rate unit I 51 11 656	12 FRU
Job time without allowance for / electrical system Flat rate unit I 61 99 000	2 FRU
Kit réparation cable/cosse Part I COSSES/CABL	Local1

— 13/11/2025 Key 151194 Km 27164 Key 10

 430 06/2027	 430 06/2027	 430 06/2027	 01/2027	 01/2027	 01/2027	 01/2027	 06/2029
---	---	---	--	--	--	--	--

— 13/11/2025 Service 151194 Km 27164 Automatic
Muzzolini,

Esch-Sur-
Alzette

 430 06/2027 ✓		 430 06/2027 ✓			 01/2027	 01/2027		 31000 06/2029			
											

—	13/11/2025	Repair	151194 Km	27164 , ESCH-SUR-ALZETTE	Job Job Job Job Job
---	------------	--------	-----------	--------------------------	---------------------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

LOCATION VOITURE	Local	1
Part I LOCATION		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Checking lighting system for correct operation	2 FRU
Flat rate unit I 63 00 009	

Voir devis ci-joint/SQ25004118	Local	1
Part I REMARQUE		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test	4 FRU
Flat rate unit I 00 00 006	

Removing and installing front and rear wheels	6 FRU
Flat rate unit I 36 10 820	

Checking function of transfer box	6 FRU
Flat rate unit I 27 00 000	

unknown fru: Essai/Contrôle final	Local	2 FRU
Flat rate unit I 00 99 001		

Boîte de transfert ok Pneus cause vibrations	Local	1
Part I REMARQUE		

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105		3 FRU
Engine oil service Flat rate unit I 00 00 610		3 FRU
Continuing vehicle test and deleting fault memory Flat rate unit I 61 00 980		3 FRU
(Statutory) vehicle inspection Flat rate unit I 00 12 159		3 FRU
RECYCLAGE FILTRE A HUILE Part I RECYCLAGE 0	Local	1
Set oil-filter element Part I 11425B4C845		1
RECYCLAGE HUILES USEES Part I RECYCLAGE 1	Local	7
BMW/Shell Oil LL19FE 0W-30 Part I HUILE01 VRA	Local	7
LIQUIDE DE REFROIDISSEMENT Part I LIQUIDE02	Local	0

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616		2 FRU
RECYCLAGE FILTRE A POLLEN Part I RECYCLAGE 1	Local	1
Set nanoparticle filter Part I 64115A29D99		1
Vehicle interior filt.f.housing cleaner Part I 83 19 2 451 455		1

— 26/06/2025 Key 122874 Km 27164 Key 10

 -3300 11.8 % 01/2027	 -3300 01/2027	 -3300 01/2027	 -3300 01/2027	 01/2027	 01/2027	 01/2027	 01/2027	 -3300 5.9 % 01/2027
---	---	---	---	--	--	--	--	---

— 26/06/2025 Service 122874 Km 27164 Automatic

Muzzolini,
Esch-Sur-
Alzette

 -3300 01/2027 ✓	 -3300 01/2027 ✓	 -3300 01/2027 ✓	 -3300 01/2027 ✓	 01/2027	 01/2027	 01/2027	 01/2027	 -3300 01/2027 ✓	 \$	 \$	 \$
--	--	--	--	--	--	--	--	---	---	---	---



—	26/06/2025	Repair	122874 Km	27164 , ESCH-SUR-ALZETTE	Job Job Job Job Job Job Job
---	------------	--------	-----------	--------------------------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit I 00 00 105	2 FRU
--	-------

Engine oil service Flat rate unit I 00 00 610	3 FRU
--	-------

RECYCLAGE FILTRE A HUILE Part I RECYCLAGE 0	Local	1
--	-------	---

Set oil-filter element Part I 11 42 7 826 799	1
--	---

RECYCLAGE HUILES USEES Part I RECYCLAGE 1	Local	7
--	-------	---

BMW/Shell Oil LL 19FE 0W-30 Part I HUILE01 VRA	Local	7
---	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter Flat rate unit I 00 00 604	6 FRU
---	-------

RECYCLAGE FILTRE A CARBURANT Part I RECYCLAGE 1	Local	1
--	-------	---

Fuel filter cartridge Part I 13 32 8 591 019	1
---	---

Self-locking hex nut Part I 64 50 9 123 157	2
--	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit I 00 00 616	2 FRU
---	-------

RECYCLAGE FILTRE A POLLEN Part I RECYCLAGE 1	Local	1
---	-------	---

Set nanoparticle filter	1
-------------------------	---

Part I 64115A29D99

Vehicle interior filt.f.housing cleaner
Part I 83 19 2 451 455

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element
Flat rate unit I 00 00 602

2 FRU

RECYCLAGE FILTRE A AIR
Part I RECYCLAGE 1

Local

1

Air filter element
Part I 13 71 8 577 170

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, vehicle check
Flat rate unit I 00 00 624

7 FRU

Job time without allowance for / maintenance
Flat rate unit I 00 99 000

3 FRU

LIQUIDE DE REFROIDISSEMENT
Part I LIQUIDE02

Local

0

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test
Flat rate unit I 00 00 006

4 FRU

Vehicle diagnosis - carrying out the ABL
Flat rate unit I 61 00 006

2 FRU

Programming/encoding control unit(s) including deleting fault memories
Flat rate unit I 61 00 730

4 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Replace left and right wiper blade
Flat rate unit I 61 61 541

1 FRU

Set of wiper blades
Part I 61 61 9 466 377

1

—

02/06/2025 Key

118453 Km

27164

Key 10

 1200 01/2027	 1200 01/2027	 1200 01/2027	 1200 01/2027	 01/2027	 01/2027	 01/2027	 01/2027	 1200 01/2027
---	---	---	---	---	---	---	--	---

—	02/06/2025	Repair	118453 Km	27164 , ESCH-SUR-ALZETTE	Job Job Job
---	------------	--------	-----------	--------------------------	-------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Main d'oeuvre carrosserie Flat rate unit I -	Local	48 FRU
Main d'oeuvre peinture Flat rate unit I MOPEINT	Local	72 FRU
RECYCLAGE PARE-CHOC Part I RECYCLAGE 0	Local	1
Panel, bumper, primed, rear Part I 51115A0BD57		1
Mount, bumper rear right Part I 51 12 8 069 248		1
Radar sensor short range Part I 66325A84D00		1
PETITES FOURNITURE Part I PETITES FOU	Local	1
MATERIEL PEINTURE Part I PEINTURE	Local	1
Forfait 1 recyclage consommable Part I RECYCLAGE 2	Local	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	14/01/2025	Key	91243 Km	27164	Key 10
---	------------	-----	----------	-------	--------

 3700 09/2026	 09/2026	 3700 09/2026	 02/2025	 1300 02/2025	 02/2025	 -5000 5.5 %	 09/2028	 33000 09/2028
--	--	--	--	--	--	---	---	---

—	14/01/2025	Key	72244 Km	27164	Key 10
---	------------	-----	----------	-------	--------

 24000 09/2026	 	 24000 09/2026	 	 	 02/2025	 02/2025	 	 60000 09/2028
--	--	--	--	--	---	---	---	--

—	14/01/2025	Service	91243 Km	27164 Muzzolini, Esch-Sur- Alzette	Manual
---	------------	---------	----------	---	--------

 3800 09/2026 ✓	 	 3800 09/2026 ✓	 	 	 02/2025 ✓	 02/2025 ✓	 -4500 09/2028 ✓	 33000 09/2028	 	 	
 											

—	14/01/2025	Repair	91243 Km	27164 , ESCH- SUR- ALZETTE	Job Job Job Job Job Job
---	------------	--------	----------	----------------------------------	--

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope Flat rate unit 00 00 105	2 FRU
Engine oil service Flat rate unit 00 00 610	3 FRU
Examen véhicule Flat rate unit 00 12 158	Local 3 FRU
RECYCLAGE FILTRE A HUILE Part RECYCLAGE 0	Local 1
Set oil-filter element Part 11 42 7 826 799	1
RECYCLAGE HUILES USEES Part RECYCLAGE 1	Local 7
BMW/Shell Oil LL 19FE 0W-30 Part HUILE01 VRA	Local 7
LIQUIDE DE REFROIDISSEMENT Part LIQUIDE02	Local 0

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service Flat rate unit 00 00 616	2 FRU
---	-------

RECYCLAGE FILTRE A POLLEN Part I RECYCLAGE 1	Local	1
Set nanoparticle filter Part I 64115A29D99		1
Vehicle interior filt.f.housing cleaner Part I 83 19 2 451 455		1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Brake fluid service Flat rate unit I 00 00 618		7 FRU
RECYCLAGE LIQUIDE DE FREIN Part I RECYCLAGE 0	Local	1
LIQUIDE DE FREIN Part I LIQUIDE01	Local	1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, front brakes Flat rate unit I 00 00 612		7 FRU
Performing vehicle test Flat rate unit I 00 00 556		3 FRU
Repair kit, brake pads asbestos-free Part I 34 11 6 889 585		1
Brake pad wear sensor, front Part I 34 35 6 870 353		1
Brake-pad paste Part I 83 19 2 158 851		1
Brake cleaner acetone-free Part I 83 19 2 413 695		1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service, rear brakes Flat rate unit I 00 00 614		9 FRU
unknown fru: Essai/Contrôle final Flat rate unit I 00 99 001	Local	3 FRU
Repair kit, brake pads asbestos-free Part I 34 21 6 890 353		1
Brake-pad sensor, rear Part I 34 35 6 870 352		1
Brake-pad paste Part I 83 19 2 158 851		1
Brake cleaner acetone-free		1

Part I 83 19 2 413 695

— Job

Description:

Considered as a repeat visit No

Customer's own words

Performing vehicle test 3 FRU
Flat rate unit I 00 00 556

Job time without allowance for / electrical system 1 FRU
Flat rate unit I 61 99 000

BMW display key 1
Part I 66125A66288

— 03/09/2024 Key 65917 Km 27164 Key 10

-3600
12.4 %
03/2026

-3600
03/2026

-3600
03/2026

-3600
03/2026

-3600
6.2 %
03/2026

— 03/09/2024 Service 65917 Km 27164 Muzzolini, Esch-Sur-Alzette Manual

-3600
03/2026
✓

-3600
03/2026
✓

-3600
03/2026
✓

-3600
03/2026
✓

-3600
03/2026
✓

— 03/09/2024 Repair 65917 Km 27164 , ESCH-SUR-ALZETTE Job
Job
Job
Job
Job

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - standard scope 2 FRU
Flat rate unit I 00 00 105

Engine oil service 3 FRU
Flat rate unit I 00 00 610

RECYCLAGE FILTRE A HUILE Local 1
Part I RECYCLAGE 0

Set oil-filter element 1
Part I 11 42 7 826 799

RECYCLAGE HUILES USEES Local 7
Part I RECYCLAGE 1

BMW/Shell Oil LL 19FE 0W-30
Part I HUILE01 VRA

Local

7

— Job

Description:

Considered as a repeat visit No

Customer's own words

Microfilter service 2 FRU
Flat rate unit I 00 00 616

RECYCLAGE FILTRE A POLLEN Local 1
Part I RECYCLAGE 1

Set nanoparticle filter 1
Part I 64115A29D99

Vehicle interior filt.f.housing cleaner 1
Part I 83 19 2 451 455

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service - air filter element 2 FRU
Flat rate unit I 00 00 602

RECYCLAGE FILTRE A AIR Local 1
Part I RECYCLAGE 1

Air filter element 1
Part I 13 71 8 577 170

— Job

Description:

Considered as a repeat visit No

Customer's own words

Service fuel filter 6 FRU
Flat rate unit I 00 00 604

RECYCLAGE FILTRE A CARBURANT Local 1
Part I RECYCLAGE 1

Fuel filter cartridge 1
Part I 13 32 8 591 019

Self-locking hex nut 2
Part I 64 50 9 123 157

— Job

Description:

Considered as a repeat visit No

Customer's own words


Service, vehicle check 7 FRU
Flat rate unit I 00 00 624

Job time without allowance for / maintenance 3 FRU
Flat rate unit I 00 99 000


LIQUIDE DE REFROIDISSEMENT
Part I LIQUIDE02

Local0

—	25/03/2024	Key	33305 Km	48713	Key 0
---	------------	-----	----------	-------	-------



—	25/03/2024	Service	33305 Km	48713 CAR AVENUE THIONVILLE , TERVILLE	Automatic
---	------------	---------	----------	---	-----------



—	25/01/2024	Key	20700 Km	27164	Key 0
---	------------	-----	----------	-------	-------



—	25/01/2024	Repair	20700 Km	27164 , ESCH- SUR- ALZETTE	Job Job Job
---	------------	--------	----------	----------------------------------	-------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Pirelli Scorpion Winter r-f Part I 85 45 2 729 329	2
---	---

Pirelli Scorpion Winter r-f Part I 85 45 2 729 330	2
---	---

Dépose/repose/remplacer pneus 20-22 pouces Part I FORFAIT 4 P	Local1
--	--------

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	04/01/2024	Key	18438 Km	27164	Key 0
---	------------	-----	----------	-------	-------



13000
06/2024





13000
06/2024







02/2025



02/2025





44000
06/2026

—	04/01/2024	Repair	18438 Km	27164 , ESCH-SUR-ALZETTE	Job Job Job Job
---	------------	--------	----------	--------------------------	--------------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / body equipment Flat rate unit I 51 99 000	120 FRU
Set trailer tow hitch electr. swivelling Part I 51125A11DF9	1
Retrofit kit, electr. additional parts Part I 71 60 2 468 520	1
Control unit, trailer tow hitch Part I 63115A056C9	1
Battery lead positive, underfloor Part I 61 12 9 442 589	1
Power distribution box, rear Part I 61 14 8 706 212	1
Wiring harness emARS underfloor Part I 61 12 9 858 141	1
Batt.voltage f.jump start terminal point Part I 61 14 6 841 552	1
Power distribution box, LIN module Part I 61355A44CE1	1
Cable connector Part I 61 13 8 353 746	10

— Job

Description:

Considered as a repeat visit No

Customer's own words

LOCATION VOITURE Part I LOCATION	Local	1
-------------------------------------	-------	---

— Job

Description:

Considered as a repeat visit No

Customer's own words

Main d'oeuvre mécanique Part I MOMEUC	Local	50
--	-------	----

— Job

Description:

Considered as a repeat visit No

Customer's own words

—	30/03/2023	Repair	3885 Km	32292 ,	Job Job
---	------------	--------	---------	---------	------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / body Flat rate unit 41 99 000	2 FRU
Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position Flat rate unit 32 00 590	16 FRU
Stripping and refitting work for painting the front left or right door Flat rate unit 51 18 750	8 FRU
Replacing front right side panel Flat rate unit 41 35 555	20 FRU
Removing and installing front bumper panel Flat rate unit 51 11 656	13 FRU
Removing and installing or replacing support for front bumper panel Flat rate unit 51 11 551	30 FRU
Replacing front bumper panel Flat rate unit 51 11 592	20 FRU
Job time without allowance for / body equipment Flat rate unit 51 99 000	2 FRU
Job time without allowance for / body equipment Flat rate unit 51 99 000	2 FRU
Replacing right LED headlight Flat rate unit 63 12 614	3 FRU
Removing and installing bonnet Flat rate unit 41 61 510	4 FRU
Replacing engine hood Flat rate unit 41 61 503	6 FRU
Removing and installing or replacing upper section of cross connection Flat rate unit 51 64 535	4 FRU
Replace lock support, right Flat rate unit 51 64 652	9 FRU
Removing and installing/replacing upper front connection Flat rate unit 51 64 525	2 FRU
Remove and install/replace left or right side sill trim panel Flat rate unit 51 71 947	6 FRU
Removing and installing rear left or right door Flat rate unit 41 52 580	3 FRU
Performing vehicle test Flat rate unit 00 00 556	3 FRU
Programming/encoding control unit(s) including deleting fault memories Flat rate unit 61 00 730	4 FRU
Performing vehicle test	3 FRU

Flat rate unit | 00 00 556

Job time without allowance for / body equipment Flat rate unit 51 99 000	15 FRU
---	--------

Job time without allowance for / body equipment Flat rate unit 51 99 000	1 FRU
---	-------

Job time without allowance for / body equipment Flat rate unit 51 99 000	1 FRU
---	-------

Number plate carrier front Part 51 11 8 069 220	1
--	---

Panel, bumper, primed, front Part 51 11 8 099 125	1
--	---

Air Curtain right Part 51 11 8 089 502	1
---	---

Bumper guide top right Part 51 11 7 421 850	1
--	---

Bumper trim front painted Part 51 11 8 099 656	1
---	---

Grille, air inlet, middle Part 51 11 8 069 211	1
---	---

Grille, side, open, right Part 51 11 8 069 210	1
---	---

Cover for air inlet right Part 51 11 8 069 214	1
---	---

Cover, fog lamp, right Part 51 11 8 099 732	1
--	---

Flap, towing lug, painted, right Part 51 11 8 069 237	1
--	---

Air inlet finisher, right Part 51 11 8 074 270	1
---	---

Adapter, right Part 51 11 7 421 636	1
--	---

Support, front Part 51 11 7 421 599	1
--	---

Impact absorber, top Part 51 11 8 069 212	1
--	---

Ultrasonic sensor black Part 66 20 9 826 784	1
---	---

Ultrasonic sensor black Part 66 20 9 826 785	1
---	---

Decoupling ring Part 66 20 9 390 408	5
---	---

Expanding rivet Part 51 12 7 004 445	10
---	----

Carrier, bumper, front bottom Part 51 11 7 421 600	1
---	---

Countersunk screw Part 07 11 9 908 698	10
---	----

Shock absorber front right Part 51 11 8 092 358	1
--	---

Bracket pedestrian protection right	1
-------------------------------------	---

Part I 51 11 7 489 472	
Ultrasonic sensor Arctic Grey Part I 66 20 9 826 959	1
Grill front Part I 51 13 8 096 590	1
Plaque Part I 51 14 7 499 154	1
Grommet Part I 51 14 1 807 495	2
Hood Part I 41 00 7 492 375	1
Sensor, front Part I 65 77 9 314 520	1
Pedestrian protection sensor PTS Part I 65765A4FC70	1
Lock top part Part I 51 23 7 347 412	1
Lock passive Part I 51 23 7 347 409	1
Sealing side panel right Part I 51 76 7 418 198	1
Seal, engine bonnet, front Part I 51 76 7 418 174	1
Headlight, laser light, right Part I 63115A55AA6	1
Control unit, front light electronics Part I 63115A0AFB0	1
LED mod.turn ind./dayt.driv.lights right Part I 63 11 9 477 988	1
LED module, daytime driving lights Part I 63 11 9 477 986	1
Set of cables, front bumper Part I 61 12 8 736 618	1
Support, fog lamp right Part I 51 11 8 069 228	1
Bumper guide right bottom Part I 51 11 7 421 854	1
Side panel, front right Part I 41 00 7 492 364	1
Wheel arch trim, front right Part I 51 77 8 099 124	1
Badge side panel Part I 51 14 8 094 236	1
Cover,wheel arch,frontsection,frnt right Part I 51 71 7 424 906	1
Cover, wheel housing, bottom right Part I 51 71 8 069 308	1
Air duct, radiator, top Part I 51 74 7 421 675	1
Air flaps, top	1

Part I 51745A29C42	
Air duct, radiator, bottom Part I 51 74 7 421 678	1
Crosslink, front Part I 51 64 7 421 711	1
Connection, front top Part I 51 64 7 421 707	1
Mounting, headlight, right Part I 51 64 7 421 710	1
Cavity protection spray Part I 83 42 2 457 337	1
Flange nut Part I 11 61 7 545 279	8
Side panel, front left Part I 41 00 7 492 363	1
Left engine hood hinge Part I 41 00 9 477 741	1
Right engine hood hinge Part I 41 00 9 477 742	1
Front left brake air duct Part I 51 74 7 421 685	1
Front right brake air duct Part I 51 74 7 421 686	1
Air duct, brake, wheel arch, left Part I 51 74 7 421 699	1
Air duct, brake, wheel arch, right Part I 51 74 7 421 700	1
Intake duct Part I 13 71 8 635 093	1
Intake grille Part I 13 71 8 635 091	1
Support Part I 51 11 7 421 839	1
Expanding nut Part I 07 14 7 306 224	5
Air duct with air flap control bottom Part I 51745A29C48	1
Fastening elements Part I 17 11 8 482 944	2
Shock absorber front left Part I 51 11 8 092 357	1
Bracket plug connection left Part I 61 13 6 835 117	1
Bracket plug connection right Part I 61 13 6 835 118	1
Bracket pedestrian protection right Part I 51 11 7 489 472	1
Duplicate information label, diesel fuel Part I 71 23 9 356 090	1
Label, coolant	1

Part | 71 23 6 995 662

— Job

Description:

Considered as a repeat visit	No
------------------------------	----

Customer's own words

Radar sensor short range Part I 66325A7A559	1
Air inlet finisher, left Part I 51 11 8 074 269	1
Flap, towing lug, painted, left Part I 51 11 8 092 124	1
Cover, fog lamp, right Part I 51 11 8 099 732	1
Cover, fog lamp right Part I 51115A08872	1
Badge side panel Part I 51 14 8 094 236	1
Outside temperature sensor Part I 65 81 6 936 953	1

— 12/12/2022 Key

3884 Km

Key 10

								
29000		29000						60000
06/2024		06/2024				02/2025	02/2025	06/2025

— 24/10/2022 Repair

18 Km

00074
Niederlassung
Frankfurt BMW
AG, Frankfurt
am Main

Job

Job

Job

— Job

Description:

Considered as a repeat visit	No
------------------------------	----

Customer's own words

Warnweste	Local	1
Part I 99 99 2 288 694		
BMW Diffusore Ambiente Stile	Local	1
Part I 99 93 3 079 000		

— Job

Description:

Considered as a repeat visit	No
------------------------------	----

Customer's own words

Emergency key 1
Part I 51 21 7 444 576

— Job

Description:

Considered as a repeat visit No


Customer's own words W.O.L.K.E AW-Nr: NL00542,W.O.L.K.E AW-Nr: NL00542,Fzg kommt aus Lager München,

Kleine Verkaufsdurchsicht - Fehlerspeich
Flat rate unit | NL00 54 2

Local

6 FRU

—	27/06/2022	Service	19 Km	04107 BMW AG NL München, München	Manual
---	------------	---------	-------	---	--------



—	24/06/2022	Repair	18 Km	04107 Niederlassung München BMW AG, München	Job Job Job
---	------------	--------	-------	---	-------------------

— Job

Description:

Considered as a repeat visit No

Customer's own words

— Job

Description:

Considered as a repeat visit No

Customer's own words Kostenlose Übergabedurchsicht,-Anzahl der Schlüssel/Ladekabel prüfen / notieren,(1)
Funkschlüssel (x)Key Card wenn vorhanden aktivieren,(1) Display Schlüssel mit separaten (1)
Metallschlüssel,-
3L Scheibenreiniger erg. (aber nicht zu buchen),- Abschleppöse prüfen
(+Gewindedurchmesser),,Navigation-Freischaltcode abfragen und e
Flat rate unit | AZ65 00 2

Local

1 FRU

Kennzeichenhalter hinten montieren (BD)
Flat rate unit | AZ00 20 0

Local

1 FRU

Free pre-delivery check
Flat rate unit | 00 00 009

9 FRU

— Job

Description:

Considered as a repeat visit No

Customer's own words

Program control unit of the head unit
Flat rate unit | 00 72 635

4 FRU

Continuing vehicle test and deleting fault memory
Flat rate unit | 61 00 980

2 FRU

Initialising/normalising slide/tilt sunroof, power window regulator and
steering column adjustment
Flat rate unit | 61 00 983

1 FRU

—	01/01/1970	Repair	3885 Km	32292 Autohaus	Job Job
---	------------	--------	---------	-------------------	------------

Becker-
Tiemann
Minden-
Lübbecke
GmbH & Co.
KG , Minden

— Job

Description:

Considered as a repeat visit No

Customer's own words

Job time without allowance for / body Flat rate unit 41 99 000	2 FRU
Carry out Kinematics Diagnosis System wheel alignment with vehicle load up to design position Flat rate unit 32 00 590	16 FRU
Stripping and refitting work for painting the front left or right door Flat rate unit 51 18 750	8 FRU
Replacing front right side panel Flat rate unit 41 35 555	20 FRU
Removing and installing front bumper panel Flat rate unit 51 11 656	13 FRU
Removing and installing or replacing support for front bumper panel Flat rate unit 51 11 551	30 FRU
Replacing front bumper panel Flat rate unit 51 11 592	20 FRU
Job time without allowance for / body equipment Flat rate unit 51 99 000	2 FRU
Job time without allowance for / body equipment Flat rate unit 51 99 000	2 FRU
Replacing right LED headlight Flat rate unit 63 12 614	3 FRU
Removing and installing bonnet Flat rate unit 41 61 510	4 FRU
Replacing engine hood Flat rate unit 41 61 503	6 FRU
Removing and installing or replacing upper section of cross connection Flat rate unit 51 64 535	4 FRU
Replace lock support, right Flat rate unit 51 64 652	9 FRU
Removing and installing/replacing upper front connection Flat rate unit 51 64 525	2 FRU
Remove and install/replace left or right side sill trim panel Flat rate unit 51 71 947	6 FRU
Removing and installing rear left or right door Flat rate unit 41 52 580	3 FRU
Performing vehicle test Flat rate unit 00 00 556	3 FRU
Programming/encoding control unit(s) including deleting fault memories Flat rate unit 61 00 730	4 FRU

Performing vehicle test Flat rate unit I 00 00 556	3 FRU
Job time without allowance for / body equipment Flat rate unit I 51 99 000	15 FRU
Job time without allowance for / body equipment Flat rate unit I 51 99 000	1 FRU
Job time without allowance for / body equipment Flat rate unit I 51 99 000	1 FRU
Number plate carrier front Part I 51 11 8 069 220	1
Panel, bumper, primed, front Part I 51 11 8 099 125	1
Air Curtain right Part I 51 11 8 089 502	1
Bumper guide top right Part I 51 11 7 421 850	1
Bumper trim front painted Part I 51 11 8 099 656	1
Grille, air inlet, middle Part I 51 11 8 069 211	1
Grille, side, open, right Part I 51 11 8 069 210	1
Cover for air inlet right Part I 51 11 8 069 214	1
Cover, fog lamp, right Part I 51 11 8 099 732	1
Flap, towing lug, painted, right Part I 51 11 8 069 237	1
Air inlet finisher, right Part I 51 11 8 074 270	1
Adapter, right Part I 51 11 7 421 636	1
Support, front Part I 51 11 7 421 599	1
Impact absorber, top Part I 51 11 8 069 212	1
Ultrasonic sensor black Part I 66 20 9 826 784	1
Ultrasonic sensor black Part I 66 20 9 826 785	1
Decoupling ring Part I 66 20 9 390 408	5
Expanding rivet Part I 51 12 7 004 445	10
Carrier, bumper, front bottom Part I 51 11 7 421 600	1
Countersunk screw Part I 07 11 9 908 698	10
Shock absorber front right Part I 51 11 8 092 358	1

Bracket pedestrian protection right Part I 51 11 7 489 472	1
Ultrasonic sensor Arctic Grey Part I 66 20 9 826 959	1
Grill front Part I 51 13 8 096 590	1
Plaque Part I 51 14 7 499 154	1
Grommet Part I 51 14 1 807 495	2
Hood Part I 41 00 7 492 375	1
Sensor, front Part I 65 77 9 314 520	1
Pedestrian protection sensor PTS Part I 65765A4FC70	1
Lock top part Part I 51 23 7 347 412	1
Lock passive Part I 51 23 7 347 409	1
Sealing side panel right Part I 51 76 7 418 198	1
Seal, engine bonnet, front Part I 51 76 7 418 174	1
Headlight, laser light, right Part I 63115A55AA6	1
Control unit, front light electronics Part I 63115A0AFB0	1
LED mod.turn ind./dayt.driv.lights right Part I 63 11 9 477 988	1
LED module, daytime driving lights Part I 63 11 9 477 986	1
Set of cables, front bumper Part I 61 12 8 736 618	1
Support, fog lamp right Part I 51 11 8 069 228	1
Bumper guide right bottom Part I 51 11 7 421 854	1
Side panel, front right Part I 41 00 7 492 364	1
Wheel arch trim, front right Part I 51 77 8 099 124	1
Badge side panel Part I 51 14 8 094 236	1
Cover,wheel arch,frontsection,frnt right Part I 51 71 7 424 906	1
Cover, wheel housing, bottom right Part I 51 71 8 069 308	1
Air duct, radiator, top Part I 51 74 7 421 675	1

Air flaps, top Part I 51745A29C42	1
Air duct, radiator, bottom Part I 51 74 7 421 678	1
Crosslink, front Part I 51 64 7 421 711	1
Connection, front top Part I 51 64 7 421 707	1
Mounting, headlight, right Part I 51 64 7 421 710	1
Cavity protection spray Part I 83 42 2 457 337	1
Flange nut Part I 11 61 7 545 279	8
Side panel, front left Part I 41 00 7 492 363	1
Left engine hood hinge Part I 41 00 9 477 741	1
Right engine hood hinge Part I 41 00 9 477 742	1
Front left brake air duct Part I 51 74 7 421 685	1
Front right brake air duct Part I 51 74 7 421 686	1
Air duct, brake, wheel arch, left Part I 51 74 7 421 699	1
Air duct, brake, wheel arch, right Part I 51 74 7 421 700	1
Intake duct Part I 13 71 8 635 093	1
Intake grille Part I 13 71 8 635 091	1
Support Part I 51 11 7 421 839	1
Expanding nut Part I 07 14 7 306 224	5
Air duct with air flap control bottom Part I 51745A29C48	1
Fastening elements Part I 17 11 8 482 944	2
Shock absorber front left Part I 51 11 8 092 357	1
Bracket plug connection left Part I 61 13 6 835 117	1
Bracket plug connection right Part I 61 13 6 835 118	1
Bracket pedestrian protection right Part I 51 11 7 489 472	1
Duplicate information label, diesel fuel Part I 71 23 9 356 090	1

Label, coolant
Part I 71 23 6 995 662

1

— Job

Description:

Considered as a repeat visit No

Customer's own words

Radar sensor short range
Part I 66325A7A559

1

Air inlet finisher, left
Part I 51 11 8 074 269

1

Flap, towing lug, painted, left
Part I 51 11 8 092 124

1

Cover, fog lamp, right
Part I 51 11 8 099 732

1

Cover, fog lamp right
Part I 51115A08872

1

Badge side panel
Part I 51 14 8 094 236

1

Outside temperature sensor
Part I 65 81 6 936 953

1